

**PUBLIC WORKS ENGINEERING DIVISION**

## Inspection Summary

Permit #: PRPWFR20171420, Public Works Infrastructure Permit - Residential  
CREEKSIDE AT RAINTREE

Address:

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DEI-Erosion Sediment Control (ESC) Inspection	Brice Lawson	Partial	Wednesday, April 04, 2018

Corrective Action Required

1 There are problems with the erosion control devices on your site.

Brice Lawson 03/27/2018 1:17 PM

Add inlet protection in front of the curb inlet in the south cul-de-sac.

Corrective Action Required

2 Your project is in violation of the Erosion and Sediment control policy.

Brice Lawson 04/04/2018 1:51 PM

Temporary sediment trap #1 has been removed. The plans show the temp. sed. trap to be removed after the uphill watershed is seeded and mulched and vegetation has been established. Properly stabilize all disturbed areas of the site.

The east perimeter silt fence just south of the mulch berm is not trenched into the ground. Make proper corrections to control erosion at this location.

Comments: