Development Services Department

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20173808, Building Permit - Residential Address: 4716 NE POCONO CIR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - Khanh Nguyen Failed Tuesday, April 17, 2018

Residential

Corrective Action Required

1 Miscellaneous Correction -Frame CSPF walls per A/4 plan detail

**for the greatroom brace walls, fill in gap between blocking and header and nail blockings to header. Framer should have installed the 1/2"-3/4" filler between the header and the blockings before nailing the straps

- -Cut joist below master toilet
- **the engineer letter says a full length joist was added, but it wasn't. Please take a look again
- -Provide solidblock support underneath foyer
- **close the return air. Outside the mechanical rm door, look up to the ceiling furdown space. See the framer pulled down the return air pan-sheet so he could add support for the beam above? I want the return air space closed off from the ceiling furdown space

**OK TO INSULATE

Comments: