

Development Services Department

220 SE Green Street Lee's Summit, MO 64063

(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20172630, Building Permit - Residential

Address: 1337 NE BRANDYWINE RD, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Khanh Nguyen	Partial	Monday, May 21, 2018

Corrective Action Required

1 Misc

FRAMING:

-Install flashing at stoop in such way that water not getting into the basement space below and concrete not in contact with wood

-Solidblock cantilevered joists below master bed

****DONT FORGET TO INSULATE AND SEAL THE CANTILEVERED FLOOR. YOU MUST INSULATE THE CANTILEVERED JOIST SPACE. PLEASE**

****OK TO ROCK**

Comments: