Development Services Department

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20161761, Building Permit - Commercial Address: 805 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Occupancy Inspection - John Borns Failed Wednesday, May 30, 2018

Codes Commercial

Corrective Action Required

1 Misc CHECK/ADJUST ALL DOOR CLOSERS

Corrective Action Required

2 Misc CHECK ALL FUNNEL DRAINS AT WATER HEATER ROOM FOR

DEBRIS; REMOVE

Corrective Action Required

3 Misc 1ST FLOOR & BASEMENT: CLEAN ALL GLASS AT HAZARDOUS

LOCATIONS TO ALLOW "TEMPERED" ETCHING TO BE VERIFIED.

Corrective Action Required

4 Misc REMOVE ALL SMOKE ALARM DUST COVERS PER LSFD.

Corrective Action Required

5 Misc JANITOR CLOSET @ 1ST FLOOR: NO TPR DOWN-PIPE APPARENT

Corrective Action Required

6 Misc 1ST FLOOR & BASEMENT: PENETRATIONS/HOLES AT CEILING AND

RATED WALLS NOT FIRE-STOPPED OR NOT PROPERLY DONE.
PROVIDE LISTING VERIFICATION FOR WHITE FOAM MATERIAL

USED AT SOME. LIPSTICKING WITH FIRE-CAULK IS NOT

APPROVED.

Corrective Action Required

7 Misc EXTEIOR HOSE BIB NEXT TO FIRE SPRINKLER ROOM NOT SECURED

TO WALL

Corrective Action Required

8 Misc ADDRESS LABELING ON HOUSE METER AT SW NOT PERMANENT

Corrective Action Required

9 Misc ALSO OBTAIN APPROVAL FROM:

- FIRE DEPT

- PLANNING

Occupancy Inspection - Fire	Michael Weissenbach	Not Ready	Wednesday, May 30, 2018
Comments:			