

Inspection Summary

Permit #: PRRES20180307, Building Permit - Residential
Address: 1809 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	John Benisch	Failed	Thursday, July 05, 2018

Corrective Action Required

1	Misc	1. overnotched stud in garage
		2. clean street

Corrective Action Required

2	Misc	1. OVER NOTCHED STUD ON EAST SIDE OF GARAGE
---	------	---

Comments: