Development Services Department

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20181348, Building Permit - Commercial Address: 699 NW BLUE PKWY, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Above Ceiling John Borns Not Ready Tuesday, July 10, 2018

Inspection

Corrective Action Required

1 Misc NOT READY FOR ABOVE-CEILING INSPECTION

Corrective Action Required

2 Misc SOME CEILING GRID NOT AT PERMANENT ELEVATION. SEE AT

RESTROOMS

Corrective Action Required

3 Misc FLEX DUCT NOT APPROVED:

- SECURE INNER LAYER, THEN OUTER LAYER WITH LISTED

MATERIAL

- HANGERS NOT MINIMUM 1-1/2" WIDE

- NOT BENDS TO BE CONSTRICTED

Corrective Action Required

4 Misc NEC 334-10 SECURING / SUPPORT OF MC ELECTRICAL CABLE:

SECURE WITHIN 12" OF BOXES AND SUPPORT AT 6' MAX

INTERVALS THEREAFTER.

Corrective Action Required

5 Misc NEC 300.11: SECURING AND SUPPORTING OF ELECTRICAL CABLE

ASSEMBLIES: MAY NOT BE SUPPORTED BY CEILING SUPPORT HANGER WIRES; SUPPORT FROM STRUCTURE, FROM OTHER COMPONENTS OF ELECTRICAL SYSTEM, OR FROM HANGERS INSTALLED FOR SUPPORT OF THE ELECTRICAL SYSTEM. SECURE

BOTH ENDS OF INDEPENDENT SUPPORT WIRES.

Corrective Action Required

6 Misc

Corrective Action Required

7 Misc SOME ELECTRICAL BOXES NOT MADE UP AND CLOSED.

In-wall Inspection John Borns Passed Tuesday, July 10, 2018

Comments: WALLS OK TO COVER. NOTE -- DRAWING STATES SOUTH DEMISING WALL MUST BE FINISHED AS RATED WALL. MUST BE APPROVABLE BEFORE & AT FINAL INSPECTION. MUD RINGS AT DEMISING WALL ARE NOT FULL DEPTH OF 5/8" GWB. ALL WILL REQUIRE SPARK RINGS.