

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Address:

once all corrective actions have been completed. Do not cover any work until approved.

This work has been inspected and the inspection results noted below. Please call for re-inspection

Inspection Item:	Inspector:	Outcome:	Date:
DEI-Sanitary Sewer Construction Inspection	Brice Lawson	Partial	Monday, July 30, 2018
Informational			

1 Brice Lawson 07/30/2018 8:04 AM

Permit #: PRSUBD20180411, Development - Subdivision
The Reserve at Stoney Creek 3rd Plat

On 7/27/18 Redford Construction informed me that they installed 60' of 8" sanitary main into MH-11. It appeared that the main was bedded in clean rock. They were in the process of installing the inverts in MH's 8, 10 and 11. Spencer with KC Testing was on site performing compaction testing on the sanitary main trench backfill. The road crossings that are near MH-10. Spencer let me know that the compaction test results were within specfications.

DEI-Detention Basin Brice Lawson Partial Monday, July 30, 2018

Informational

1 Brice Lawson 07/30/2018 8:19 AM

On 7/27/18 silt fence has been installed below the permanent detention basin. The silt fence has been installed in a continuous run. It does not appear that there is enough ESC measures in place to control erosion in and below the detention basin. I informed Tom C. of this and he is aware and plans to follow up with contractor.

Comments: