Development Services Department

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20180820, Building Permit - Residential Address: 4071 NE TIMBERLAKE CT, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Underslab Plumbing Khanh Nguyen Failed Wednesday, August 22, 2018

Inspection - Residential

Corrective Action Required

1 Misc -PROTECT WATER LINE AT SLAB PENETRATION

-SLAB ON FILL AT BACK OF HOUSE. SUPPORT DRAINAGE PIPE

EVERY 4 FT

Erosion Control Khanh Nguyen Failed Wednesday, August 22, 2018

Corrective Action Required

1 DCM5 Erosion Control REQUESTED INSPECTION(S) DENIED DUE TO DEFICIENT EROSION

CONTROL INSTALLATION.

Comments: