

Development Services Department

220 SE Green Street Lee's Summit, MO 64063

(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20181168, Building Permit - Residential

Address: 1313 NE BRANDYWINE RD, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Khanh Nguyen	Failed	Thursday, August 30, 2018

Corrective Action Required

1	Misc	-2x10 @12" oc above garage per plan -ADDENUM: fix the framing at attic access above the garage. The joist was cut short (by the garage door guy?) and has no hanger support. -Install hanger for double joist connection at stair. As an alternative, the framer can install Simpson L support brackets on both sides of the double joist -Resecure&support wiring above 2nd fl. The framer removed the wiring when relocate theroof supporting struts to the bearing wall
---	------	--

****OK TO INSULATE**

Comments: