

**PUBLIC WORKS ENGINEERING DIVISION**

## Inspection Summary

Permit #: PRSITE20171319, Development - Site

Address: 2900 NE INDEPENDENCE AVE, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

<b>Inspection:</b>	<b>Inspector:</b>	<b>Outcome:</b>	<b>Date:</b>
DEI-Punch List Inspection	Steve Robbins	Partial	Thursday, August 30, 2018

Informational

1. Vegetation needs to be established along the back side of the parking lot.
2. The ADA ramps need to have the plastic removed.
3. There is some cracked sidewalk on the east-back side of the parking lot going by the approach.
4. Where the water line was tied in and replaced the concrete has settled or cracked.
5. The erosion control needs to be maintained and removed when vegetation has been established.

**Comments:**