## **Development Services Department**

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

## **Inspection Summary**

## Permit #:PRCOM20182297, Building Permit - Commercial Address: 910 NW BLUE PKWY, Unit:Y, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
In-wall Inspection	John Borns	Failed	Monday, September 17, 2018
Corrective Action Required			
1 Misc	Si Ir T	EC 334-10 SECURING / SUPPO ECURE WITHIN 12" OF BOXES A NTERVALS THEREAFTER. COLOF O RESIST TUGGING. USE CLAM VITHIN 12" OF BOX ENTRY.	ND SUPPORT AT 6' MAX ADO JIMS DO NOT SECURE MC
Corrective Action Required			
2 Misc	A F/ P SI M E	BS / PEX / COPPER PLUMBING ACE OF FRAMING TO RECEIVE S ROTECT PIPE WITH MINIMUM HIELD PLATES. SHIELD PLATES S IEMBER WHERE THE PIPE PENE XTEND A MINIMUM OF 2" ABC	ON FROM PENETRATION OF PVC / PIPE LESS THAN 1-1/2" FROM SCREWED OR NAILED COVERING: 1/16" THICK HARDENED STEEL SHALL COVER THE AREA OF THE TRATES. SHIELD PLATES SHALL VE BASE PLATES / TRACKS AND ISE "BOCA" PLATES). CHECK ALL.

Comments: