

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRRES20181586, Building Permit - Residential

This wor	k has been inspecte	ed and the inspection res	ults noted below. Please c	all for re-inspection
once all corrective actions have been completed. Do not cover any work until approved.				
Inspection Item: Inspection:		Inspector:	Outcome:	Date:
Driveway Inspection		Steve Robbins	Partial	Tuesday, October 02, 2018
Informati 1	tional The driveway has been formed and appears to have 4" of compacted rock. Everthing looks good and is ready to pour.Steve Robbins 10/02/2018 8:27 AM			
DEI-Side	walk Inspection	Steve Robbins	Partial	Tuesday, October 02, 2018
Informati	onal			
1	The sidewalk has been formed and has 4" of rock that has been compacted. At the end of the property line there is a MH that needs to be raised up, I am going to speak with Holthouse about this situation. I told them they can pour up to 2 panels before the MH.Steve Robbins 10/02/2018 8:34 AM			
Commer	nts:			