## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

## **Inspection Summary**

Permit #:PRSITE20182837, Development - Site Address: 450 SW LONGVIEW BLVD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
DEI-Sto	rm - Pipe	Ronald Paynter	Partial	Wednesday, October 31, 2018	
Corrective Action Required					
1	Misc			ble goes, trying to remove it hole was set. Photos attached.	
Corrective Action Required					
2 Misc			Ran into rock where the manhole goes, trying to remove it now.		
Corrective Action Required					
3 Misc		equi	Set first nyloplast drain inlet, ran into more rock. Had equipment problems. Going to pour collars and invert for manhole later today.		
Corrective Action Required					
4	Misc	mecl	irst nyloplast drain inlet, r nanical problems with equ nvert for manhole later to	ipment. Going to pour collars	
Corrective Action Required					
5	Misc	mecl	irst nyloplast drain inlet, r nanical problems with equ nvert for manhole later to	ipment. Going to pour collars	

Comments: