



DEVELOPMENT SERVICES

Inspection Summary

Permit #:PRRES20182892, Building Permit - Residential
Address: 4419 SW AMETHYST DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Footing Inspection - Residential	Jason McRoy	Partial	Thursday, November 01, 2018

Corrective Action Required

1 Misc

Footing was inspected, the foundation was over excavated, as a result 2 pier pads IN GARAGE were not able to be formed and poured at the time of inspection.

at such time as the foundation is able to be back filled the 2 additional pier pads should be formed and called back in

FOOTING IS OK TO POUR.

Comments: