

Inspection Summary

Permit #: PRRES20183809, Building Permit - Residential

Address: 4521 SW NAUTILUS PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
Erosion Control	John DiMauro	Failed	Thursday, March 07, 2019

Corrective Action Required

1 John DiMauro 03/07/2019 11:56 AM

EROSION CONTROL REQUIRED. NO FURTHER INSPECTIONS WILL BE PERFORMED UNTIL EROSION CONTROL IS INSTALLED AND IN COMPLIANCE.

EROSION CONTROL DEVICES NEED TO BE INSTALLED ALONG THE BACK SIDE OF THE PROPERTY TO PROTECT THE CREEK FROM FURTHER SILTATION.

Comments: