

PLANS REVIEW CONDITIONS

Permit No:	PRCOM20182860	Date:	April 02, 2019
Project Title:	TIKKA TWIST	Applicant:	
Location:	697 NW BLUE PKWY, LEES SUMMIT, MO 64086		GOAL FIRE PROTECTION, LLC 13100 SWARTZ RD BONNER SPRINGS, KS 66012
Type of Work:			
Occupancy Group:	A-2		
Description:	TENANT FINISH FOR A NEW RESTAURANT	Primary:	(913) 441-3390
Construction Type:	Type IIB (Unprotected)		
Map Page:	195A		

Listed below are requirements from our department for the project noted above. If you have any additional questions, please contact our department for further clarification.

Sprinkler Plan Review

Reviewed By: Joe Dir

Released for Construction

1. 2018 IFC 901.6- Inspection, testing and maintenance. Fire detection, alarm and extinguishing systems shall be maintained in an operative condition at all times, and shall be replaced or repaired where defective. Not required fire protection systems and equipment shall be inspected, tested and maintained or removed.

ACTION REQUIRED:(verified at inspection)

The existing fire sprinkler system riser shall be current with annual service. A current service tag shall be posted on the riser.

The applicant understands that the requirements listed above must be corrected to conform to applicable City Codes and Ordinances.