

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20181851
Address: 1531 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Plot Plan Inspection	Jason McRoy	Failed	Friday, April 26, 2019

Corrective Action Required:

- | | | |
|---|------|--|
| 1 | Misc | 1.THERE IS ASMALL SINK HOLE LOCATED IN THE FRONT YARD AT SOUTHEAST SIDE OF YARD CLOSE TO THE WATER METER.
2.THERE IS A LARGE SINK HOLE ON NORTHWEST SIDE OF FRONT YARD LEFT OF DRIVEWAY.
3. CONFIRM 6" OF FALL IN FIRST 10' IN BACK OF HOUSE |
|---|------|--|

Comments: