

# Inspection Summary

Permit #: PRSUBD20180796, Development - Subdivision  
Hawthorn Ridge 1st Plat - onsite  
Address: 1601 SW HOOK RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DE - Erosion Sediment Control (ESC) Inspection	Steve Robbins	Failed	Monday, May 20, 2019
Corrective Action Required			
1	John DiMauro 08/17/2018 11:16 AM		

Your project is in violation of the Erosion and Sediment control policy.

There is debris, mud and silt running off site and onto SW Hook Rd. Please clean the debris and silt from the road and make all necessary corrections to the erosion control devices immediately.

Corrective Action Required

2	We continue to get complaints from 1615 Hook Road. I have been out to take pictures , there is silt and straw coming onto the property of 1612 Hook. I have spoke with Emery Sapp and they were going to come out last week and do some clean-up and erosion control but did not make it out yet. Over the weekend they had more silt coming onto their property , I call Travis Ruf today and he said he would do their best to get a crew out this afternoon before the rain comes. The home owners are very concerned about the rain that is coming in. Steve Robbins 05/20/2019 4:13 PM
---	---

DE - Sidewalk Inspection	Steve Robbins	Passed	Monday, May 20, 2019
--------------------------	---------------	--------	----------------------

Informational

1	All the sidewalks appear to be installed and have passed ada standards.
---	---

Comments:

