

# Inspection Summary

Permit #: PRSUBD20162865, Development - Subdivision  
MONTICELLO 3RD PLAT

Address:

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DE - Sanitary Sewer Construction Inspection	Steve Robbins	Partial	Tuesday, May 21, 2019
Corrective Action Required			
1	The camera test that was done revealed that MH 6-029 was repaired for infiltration for the 3rd time and needs to be checks again. The sag for MH 06--70 was repaired and waiting for the 30 days for another camera test.		
Informational			
2	Sent Brent an e-mail to let him know the 30 days are up for the sag that has been repaired and to also check the infiltration on the existiing MH.Steve Robbins 05/21/2019 3:53 PM		

Comments: