

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20183200
Address: 1706 NW OBRIEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	John Borns	Failed	Tuesday, August 06, 2019

Partial Correction:

1	Misc	ABOVE CEILING ONLY - APPROVED TO ROCK LIDS: EAST WING, ROOMS 135-148; [116-119; 121-124; 126; 128; 130-132; CENTER, SPACES 104-108; 125; 127;
---	------	--

Corrective Action Required:

2	Misc	IN-WALL @ EAST WING: IBC 2308.9.10, IRC R602.6: OVER-BORED (>40% BEARING; >60% NON-BEARING) (5/8" MINIMUM TO EDGE) STUDS MUST BE DOUBLED OR REINFORCED WITH APPROVED STUD SHOE.
---	------	---

Corrective Action Required:

3	Misc	IN-WALL @ EAST WING: COMPLETE FIRE-BLOCKING OF TOPS OF DEAD SPACES
---	------	--

Corrective Action Required:

4	Misc	IN-WALL @ EAST WING: COMPLETE ALL IN-WALL WIRING. NOT COMPLETE AT BA'S AND AT A147 BR
---	------	---

Comments: