CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20183200 Address: 1706 NW OBRIEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspectior	1:	Inspector:	Outcome:	Date:
All Rough Commerc	Inspection - ial	John Borns	Failed	Wednesday, August 07, 2019
Partial Correction:				
1		INSPECTED ABOVE CEILING ONLY - APPROVED TO ROCK LIDS: EAST WING, ROOMS 135-148; [116-119; 121-124; 126; 128; 130-132; CENTER, SPACES 104-108; 125; 127;		
Corrective Action Required:				
2		IN-WALL @ EAST WING: IBC 2308.9.10, IRC R602.6: OVER-BORED (>40% BEARING; >60% NON-BEARING) (5/8" MINIMUM TO EDGE) STUDS MUST BE DOUBLED OR REINFORCED WITH APPROVED STUD SHOE.		
Corrective Action Required:				
3	Misc	IN-WALL @ EAST WING: CO	OMPLETE FIRE-BLOCKING OF	TOPS OF DEAD SPACES
Corrective Action Required:				
4	Misc	IN-WALL @ EAST WING: SE	CURE MC CABLE WITHIN 12	" OF ENTRY TO BOXES

Comments: