

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20170403

Address: 3540 SW HOLLYWOOD DR, Unit:4, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Commercial	Brandon Kalwei	Failed	Monday, August 26, 2019

Corrective Action Required:

1	Misc	204-205 firecaulk furnace room 204 sprinkler ring hall Sprinkler ring hall 2 Stair tower 2 Tower 2 exit light and exterior light Room 300 -outlet in spare bathroom on right side needs to be gfci protected Room 105 -carbon monoxide detector needs to be in great room, it is installed in the bedroom Room 103 -clean out in bedroom needs cover Room 101 -bathroom GFCI not working Storage Room S9 -light hanging Storage room 19 -clean out needs cover South Mechanical room -secure WHIP within 12" of boxes, fire caulk around heat ducts, Room 107 Need clean out cover underneath sink in bathroom, cover over vent in
---	------	---

bathroom, smoke and C/o detectors need to be swapped in bedroom and main room, vent fan not working in front bathroom

Room 206

-smoke/co combo unit will need to be switched with smoke detector. Main room and bedroom

Room 306

-vent fan not working in bathroom

Room 307

-fire caulk needed at the ceiling in mechanical room, smoke detector covered in bedroom, vent fan not working in far bathroom

Comments: