CITY OF LEE'S SUMMIT

Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20190763

Address: 4836 NE JAMESTOWN DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Khanh Nguyen Failed Monday, September

Residential 09, 2019

Corrective Action Required:

1 Misc FRAMING:

-Provide plan on site

- -Check plan for number of stud support under garage I beam
- -Security blocking for garage door -Install exterior windows and door
- -Over notched rafters at triple roof beam support
- -Brace ends of IvI beams from rotation
- -Fb kitchen wall from roof; Fb foyer wall from roof
- -Reinforce non-continuous studs at rear dining exterior wall
- -Remove construction materials from roof
- -Make sure the maximum stair riser height is no more than 3/8"
- -Expose to verify support for IvI beam at stair beam pocket
- -Fb basement wall vertically at ten ft or less; Fb basement bathroom and closet wall from ceiling furdown space
- -Anchor basement steel columns

ELECTRICAL:

- -At rear basement bedroom ceiling, securely fasten wiring per code
- -Protect wiring at ceiling lights outside basement bedrooms
- -Parallel electrical inside return air space outside basement bedrooms and above wet bar

MECHANICAL: -Pan off return air space from soffit space outside rear basement bedrooms
PLUMBING: -Complete gas line to fireplace; protect wardflex at fireplace
**OK TO INSULATE

Comments: