CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20191953

Address: 1708 NW CHIPMAN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Above Ceiling Inspection John Borns Failed Friday, October 04,

2019

Corrective Action Required:

1 Misc REMOVE ABANDONED MATERIALS AND EQUIPMENT:

- LIGHT-GUAGE STEEL FRAMING MEMBERS

- PLUMBING AND SPRINKLER PIPE

- HVAC DUCT - HANGERS - ETC

Corrective Action Required:

2 Misc ATTACH NO HANGERS TO ROOF DECK UNLESS APPROVED IN WRITING BY

ENGINEER OF RECORD

Corrective Action Required:

3 Misc HANGING M/E/P SYSTEMS FROM UPPER OR LOWER HORIZONTAL JOIST

BRIDGING NOT APPROVED UNLESS SO STATED BY ENGINEER OF RECORD.

Corrective Action Required:

4 Misc SUPPORT OF ARCH CEILING BY LIGHT-GUAGE STEEL STUD SECTIONS SPANNED

HORIZONTALLY FROM JOIST TO JOIST NOT APPROVED UNLESS APPROVED IN

WRITING BY ENGINEER OF RECORD.

SUPPORT LEVEL CEILING FROM HANGERS AT 4' O/C EACH WAY UNLESS

PRESCRIBED OTHERWISE BY ENGINEER OF RECORD.

Corrective Action Required:

5 Misc CLOSE ALL OPENINGS AT COMMON WALLS

Corrective Action Required:

6 Misc MAINTENANCE ACCESS AND WORKING SPACE AT WATER HEATERS NOT

APPROVED.

Corrective Action Required:

7 Misc INSTALL HANGERS FOR PLUMBING PIPE AND HVAC DUCT PER IPC AND

IMC/SMACNA. HANGERS MUST BE TAUT IN ORDER TO PROVIDE SUPPORT.

Corrective Action Required:

8 Misc ACCESS PANELS OF ADEQUATE SIZE AND PROXIMITY ARE REQUIRED FOR EVERY

ELECTRICAL JUNCTION BOX, DISCONNECT, AND OTHER EQUIPMENT AND

DEVICES.

Corrective Action Required:

9 Misc

ONE ELECTRICAL JUNTION BOX IS COVERED WITH UNKNOWN MATERIAL.

Corrective Action Required:

10 Misc NO APPROVED DRAWINGS ARE FOUND ON FIRE DEPARTMENT RECORD FOR

SPRINKLER SYSTEM OR FOR ALARM SYSTEM. BEFORE REQUESTING

RE-INSPECTION SUBMIT AND OBTAIN APPROVAL OF SAME.

Corrective Action Required:

11 Misc <u>REAR AREA ONLY (NOT INCLUDING NE HALL)</u>:

- IDENTFY PVC PIPE STUBBED AND CAPPED

- SPRINKLER SYSTEM DRAWINGS MUST BE APPROVED

- REMOVE ABANDONED SPRINKLER PIPE BRANCHES

- SUPPORT ELECTRICAL CONDUIT

- SUPPORT HVAC FLEX DUCT W/ 1-1/2" WIDE STRAPS

Comments: