CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20191576 Address: 1808 SW MERRYMAN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Khanh Nguyen	Failed	Friday, October 25, 2019
Corrective Action Required:			
1 Misc	 FRAMING: Screw rear patio posts to roof beams against uplift Garage exterior wall studs notched more than 25% Strap the garage portal brace walls at inner sides Install steel column for garage I beam and anchor to floor; complete furring around I beam Fb duct chase from ceiling space; Fb rear living rm spaces from soffit Install (3)2x4 support for IvI at stair Install (3)2x4 stud support for IvI at front dining; fully nail hanger above Install hangers for 3x joist at IvI connection above foyer; install hanger for adjacent joist Nail 2x6 corner studs at stair per code Provide roof ventilation per code Fb basement wall vertically at max ten ft interval; Fb basement wall from soffits 		
	MECHANICAL: -Connect duct to bath fan 2nd fl bathroom		
	ELECTRICAL: -Protect wiring within six ft of garage attic access		

-Protect home runs at master bedroom

-Securely fasten wiring in basement ceiling fur-down, not resting on it -Smoke alarm in basement bedroom must be min 4" away from soffit wall -Provide proper clearance of light to storage space in basement bedroom closet per code

PLUMBING:

-Protect plumbing at kitchen duct chase

-Protect gas csst line at fireplace

-Gas line to fireplace located outside basement ceiling joist space. Redo gas line to fireplace and retest. Do not notch joist.

-Clean out at bottom of waste stack located in basement family room shall be accessible

****OK TO INSULATE**

Comments: