CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192047

Address: 300 SW BLUE PKWY, Unit:B, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Occupancy Inspection - Codes John Borns Failed Wednesday, November

Commercial 13, 2019

Corrective Action Required:

1 Misc ROOFTOP GAS PIPING:

SOME SUPPORT BLOCKS DO NOT HAVE STRAPS
SOME SUPPORT BLOCK STRAPS DO NOT HAVE BOLTS
ONE OR MORE DIRT LEGS DO NOT HAVE CLEARANCE

Corrective Action Required:

2 Misc ROOFTOP CLEANUP: REMOVE ALL EXCESS MATERIAL AND DEBRIS ON TENANT

FOOTPRINT

Corrective Action Required:

3 Misc STOREFRONT GLAZING MUST BE TEMPERED. NOT CLEANED TO DETERMINE.

Corrective Action Required:

4 Misc LS CODE OF ORDINANCES 17-309: DISPLAY OF "NO SMOKING" SIGN(S)

REQUIRED AT PUBLIC ENTRY(IES). SHALL BE CONSPICOUS AT EACH PUBLIC

POINT OF ENTRY.

Corrective Action Required:

5 Misc ANSI 603.3 MOUNTING OF MIRRORS AT ACCESSIBLE RESTROOMS: SET BOTTOM

OF VIEWING SURFACE <= 40" AFF

Corrective Action Required:

6 Misc ICC A117.1 609.4: VERTICAL GRAB BARS NOT INSTALLED AT ACCESSIBLE

RESTROOMS

Corrective Action Required:

7 Misc ELECT RECEPTS LOOSE AT:

- SHOWROOM N WALL

- MICROWAVE AT BREAK ROOM

Corrective Action Required:

8 Misc JANITOR SINK NOT INSTALLED AT STOCK ROOM

Corrective Action Required:

9 Misc OBTAIN APPROVAL FROM LSFD

Comments: