	Inspection	Summary	
Permit #	t: PRSUBD20162865, Development - Subdivisi MONTICELLO 3RD PLAT :	on	
	k has been inspected and the inspection resu corrective actions have been completed. Do		•
Inspection Inspection		Outcome:	Date:
DE - Erosion Sediment Control Steve Robbins (ESC) Inspection			
_		Passed	Monday, January 06, 2020
(ESC) Ins	re Action Required A complaint from 4712 Pocono Circ was red houses behind. I checked the complaint and 4709, and 4713 and has filled in the swale to silt fence up as of now but it appears that in swale and has come over in the yard of 471	reived about silt running to d it appears that silt has ra hat runs between the hou thas failed recently as the 2 Pocono circ. I will reach	January 06, 2020 Their yard from the in down from lot 4705 ises. The houses have re is a lot of silt in the out to the developer
(ESC) Ins Correctiv 1	spection The Action Required A complaint from 4712 Pocono Circ was red houses behind. I checked the complaint and 4709, and 4713 and has filled in the swale to silt fence up as of now but it appears that in	eived about silt running to d it appears that silt has ra hat runs between the hou has failed recently as the 2 Pocono circ. I will reach ders to get this taken care	January 06, 2020 Their yard from the in down from lot 4705 ises. The houses have re is a lot of silt in the out to the developer e of.