

Inspection Summary

Permit #: PRSITE20183936, Development - Site
Higdon Construction
Address: 1450 SE BROADWAY DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DE - Erosion Sediment Control (ESC) Inspection	Steve Robbins	Failed	Thursday, January 16, 2020

Corrective Action Required

- 1 The large pile of dirt next to the building needs to have silt fence around it. Contractor has stated to the inspector that he would be moving the dirt soon, this has not happened, so some type of ESC needs to be installed.

Comments: