


Streets of West Pryor Sewer Bond Inspection



Debris in lines
and MH needs flushed

R. McCormick

CCTV pictures of 21-119
For 30155

X

Work Order		Surveyed On 2019/11/08	
Street Name	Streets of West Pryor	Video	
City Name	Lees Summit	Weather	
Location			
From Manhole	21-119	To Manhole	21-120
		Survey Direction Downstream	

Setup 13

Counter 0.0 Ft



D:\Snaps\96901\27.jpg 2019/11/08

Pipe Details:

Year Laid	Shape	Size 8	By ins
Material	Lining	Use	

Observation: Code not found

Comments:



PipeLogix Inc.
Phone:866-299-3150
Fax:760-406-6023

CCTV pictures of 21-122 X
For 30155

Work Order		Surveyed On 2019/11/11	
Street Name	Streets of West Pryor	Video	
City Name	Lees Summit	Weather	
Location			
From Manhole 21-122	To Manhole 21-123	Survey Direction Downstream	

Setup 5 Counter 0.0 Ft



D:\Snaps\96901\29.jpg 2019/11/11

Pipe Details:

Year Laid	Shape	Size 8	By ins
Material	Lining	Use	

*Incline is at 2.65
at end of pipe.*

Observation: Code not found

Comments:



PipeLogix Inc.
Phone:866-299-3150
Fax:760-406-6023



0.28 is the incline it should be negative

this number goes up to 2.21 at the end of pipe!

CCTV pictures of 21-118 X
For 30155

Work Order		Surveyed On 2019/11/08
Street Name	Streets of West Pryor	Video
City Name	Lees Summit	Weather
Location		
From Manhole 21-118	To Manhole 21-119	Survey Direction Downstream

Setup 14 Counter 0.0 Ft



D:\Snaps\96901\26.jpg 2019/11/08

Incline is at 1.6 at end of pipe

Pipe Details:

Year Laid	Shape	Size 8	By ins
Material	Lining	Use	

Observation: Code not found

Comments:



PipeLogix Inc.
Phone: 866-299-3150
Fax: 760-406-6023

CCTV pictures of 21-117 X
For 30155

Work Order		Surveyed On 2019/11/01	
Street Name	Streets of West Pryor	Video	
City Name	Lees Summit	Weather	
Location			
From Manhole	21-117	To Manhole	21-118
		Survey Direction Downstream	

Setup 15 Counter 0.0 Ft



D:\Snaps\96901\23.jpg 2019/11/01

Pipe Details:

Year Laid	Shape	Size 8	By ins
Material	Lining	Use	

Observation: Code not found

Comments:



PipeLogix Inc.
Phone:866-299-3150
Fax:760-406-6023