

1100 W Cambridge Circle Drive, Suite 700 Kansas City, Kansas 66103 913.627.9040

DAILY FIELD REPORT

CLIENT: Pearl Real Estate Company PROJECT: Summit of West Pryor

919 N East Street Apartments

Indianapolis, Indiana 46202 Lee's Summit, Missouri

ATTN: Brad Richey DATE: 12/4/19

CFS

WEATHER: Sunny PERSONNEL: M. Simpson

TEMPERATURE: 35-65 REPORT #: 19-1125-dr- 23

TYPE OF SERVICE BEING PERFORMED

MASONRY GROUT DEVIATION FOUND: NO

MASONRY REINFORCING STEEL DEVIATION CORRECTED:

CONCRETE PLACEMENT ORIGINAL DEVIATION DATE:

CONCRETE REINFORCING STEEL

WORK ACCOMPLISHED THIS DATE:

- Monitored placement of grout and inspected reinforcing steel at A line/4.2 TO 9.2, (92.8 96.8 AFF) Wall is grouted solid.
- · Reinforcing steel verified to be in compliance with plans and specifications.
- Monitored placement of concrete for 4.3 line /C, D, E, F; 4.5 line/C, D, E, F; 2.1 line/C, D, E, F, G, & G.9; 3.1 line/C, D, E, F, G, & G.9; 4.1 liner/C, D, E, F, G, & G.9
- · One set of 4 test cylinders were cast. Slump and temperature met job requirements.
- · Reinforcing steel verified to be in compliance with plans and specifications.