

February 6, 2020

City of Lee's Summit
Codes Administration
PO Box 1600
Lee's Summit, Missouri 64063

Attention: Mr. Mark Dunning, Mark.Dunning@CityofLS.net

RE: Special Inspection Services
DCI – Lee's Summit
2001 NW Shamrock Road
Lee's Summit, Missouri
Terracon Project No. 02191565

Mr. Dunning:

Terracon has been retained by Axiom Northwest Corporation to provide construction observation and testing services in conjunction with Special Inspection Requirements of the 2012 IBC Code, Section 1704 for the following items.

- | | |
|--|--|
| <input checked="" type="checkbox"/> Placement of Reinforced Concrete | <input type="checkbox"/> Shop Inspection of Precast |
| <input checked="" type="checkbox"/> Testing of Reinforced Concrete | <input type="checkbox"/> Erection of Precast Concrete |
| <input checked="" type="checkbox"/> Placement of Reinforcing Steel | <input checked="" type="checkbox"/> High Strength Bolting |
| <input type="checkbox"/> Placement of Prestressing Steel | <input checked="" type="checkbox"/> Structural Welding |
| <input checked="" type="checkbox"/> Bolts Installed in Concrete | <input checked="" type="checkbox"/> Steel Frame Inspection |
| <input checked="" type="checkbox"/> Verification of Soils | <input type="checkbox"/> Shop Inspection Bar Joist |
| <input checked="" type="checkbox"/> Engineered Grading and /or Filling | <input type="checkbox"/> Shop Inspection Metal Building |
| <input type="checkbox"/> Drilled Piers, Piles, Caissons | <input type="checkbox"/> Shop Inspection of Structural Steel |
| <input type="checkbox"/> Earth-Retaining Structure | <input type="checkbox"/> Spray-Applied Fireproofing |
| <input type="checkbox"/> Detention Basin | <input type="checkbox"/> Structural Masonry |
| <input type="checkbox"/> Seismic Resistance | <input type="checkbox"/> Smoke Control |
| <input checked="" type="checkbox"/> EIFS | <input type="checkbox"/> Post-Installed Anchor Installation |
| <input checked="" type="checkbox"/> Air Barrier Installation | <input checked="" type="checkbox"/> Wood Frame Inspection |

If there are any questions concerning this letter or if we can be of further service in any way, please do not hesitate to contact us.

Sincerely,

Terracon

Justin L. Clay, PE
Project Engineer

