Permit #: PRPWFR20171420, CREEKSIDE AT RAINTREE Address: This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.							
				Inspection Iter Inspection:	n: Inspector:	Outcome:	Date:
				DE - Erosion S (ESC) Inspection	ediment Control on	Failed	Friday, February 21, 2020
Corrective Action You	on Required r project is in violation of the Erosion	n and Sediment control policy	<i>/</i> .				
	re are a number of lots in the subdivected, installed & maintained.	rision that need erosion contr	ol devices to be				
The	re are a number of lots that need th	e correct construction entran	ces to be installed.				
The	streets are covered in mud, silt and	loose rock and need to be cle	eaned asap.				
corr	weather forecast is calling for significations to the erosion control effort zing of permits.		•				
Noti	fy builders with active permits to m	ake corrections to their ESC c	levices and keep the				