

# Inspection Summary

Permit #: PRRES20192709, Building Permit - Residential

Address: 4516 SW NAUTILUS PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
Erosion Control	John DiMauro	Failed	Friday, February 21, 2020

Corrective Action Required

1 Failed erosion control, install erosion control on south side of lot and protect around big mound of dirt in back yard. Erosion control at front of lot is failing, clean up street of dirt and debris. All Must be done before future inspections

Corrective Action Required

2 DEFICIENT EROSION CONTROL INSTALLATION. NO FURTHER INSPECTIONS UNTIL ADEQUATE EROSION CONTROL PROVIDED.

CLEAN STREETS OF MUD AND SILT.

CONTROL MUD, ROCK AND DEBRIS FROM LEAVING YOUR SITE.

Comments: