

Inspection Summary

Permit #: PRSITE20180219, Development - Site
MERIDIAN AT VIEW HIGH APARTMENTS
Address: 201 NW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DE - Erosion Sediment Control (ESC) Inspection	Steve Robbins	Failed	Thursday, February 27, 2020

Corrective Action Required

- 1 I was informed by the building inspector that the site was needed to be cleaned up. The site is in violation, mud and silt on the roads, gutter buddies need to be cleaned out and any dirt piles need to be protected by silt fence so they are not draining down the storm. Please take care of this matter right away. We will check back on Monday March 2. If this matter is not resolved inspections by the building inspector may be denied until it is cleaned up.

Comments: