

1100 W Cambridge Circle Drive

Suite 700

Kansas City, Kansas 66103

913.627.9040

2121 Moodie Road Lawrence, Kansas 66046 2011 NW Topeka Blvd Topeka, Kansas 66608

Apartments

785.856.9600 785.270.6447

DAILY FIELD REPORT

CLIENT: Pearl Real Estate Company PROJECT: Summit of West Pryor

919 N East Street

Indianapolis, Indiana 46202 Lee's Summit, Missouri

ATTN: Brad Richey DATE: 2/27/20

CFS

WEATHER: Sunny PERSONNEL: M. Simpson

TEMPERATURE: 30-50 REPORT #: 19-1125-dr- 84

TYPE OF SERVICE BEING PERFORMED

SOILS COMPACTION MONITORING DEVIATION FOUND: NO

MASONRY GROUT / REINFORCING STEEL DEVIATION CORRECTED:

CONCRETE PLACEMENT / REINFORCING STEEL ORIGINAL DEVIATION DATE:

CONCRETE CYLINDER PICK UP

WORK ACCOMPLISHED THIS DATE:

- · Monitored placement and compaction of fill for backfill exterior wall J.
- · Monitored placement of grout and inspected reinforcing steel at Cmu grout inspection on elevator A walls, observed grout placed from elevation 100.0 to 104.0 and 104.0 to 10 8.0
- · Slump met specifications.
- · Reinforcing steel verified to be in compliance with plans and specifications.
- Monitored placement of concrete for Elevator C pit floor and columns at 7.9/J, 5 /J and vent shafts 5.6 /J and 7.5 /J. And column at 5.2/J.
- · One set of 4 test cylinders were cast. Slump and temperature met job requirements.
- · Reinforcing steel verified to be in compliance with plans and specifications.
- · Cylinder pick up of grout set #237 and concrete set #249.