

1100 W Cambridge Circle Drive

Suite 700

Kansas City, Kansas 66103

913.627.9040

2121 Moodie Road Lawrence, Kansas 66046 2011 NW Topeka Blvd Topeka, Kansas 66608

785.856.9600 785.270.6447

DAILY FIELD REPORT

CLIENT: Pearl Real Estate Company PROJECT: Summit of West Pryor

919 N East Street Apartments

Indianapolis, Indiana 46202 Lee's Summit, Missouri

ATTN: Brad Richey DATE: 2/11/20

CFS

WEATHER: Overcast PERSONNEL: M. Simpson

TEMPERATURE: 32-45 REPORT #: 19-1125-dr- 70

TYPE OF SERVICE BEING PERFORMED

CONCRETE PLACEMENT DEVIATION FOUND: NO

CONCRETE REINFORCING STEEL DEVIATION CORRECTED:

MASONRY GROUT / REINFORCING STEEL ORIGINAL DEVIATION DATE:

OTHER EPOXY INSTALLATION

WORK ACCOMPLISHED THIS DATE:

- · Monitored placement of grout and inspected reinforcing steel at CMU walls from B.3-1 to 1.5A, elevation 88.00 to 92.00
- · Reinforcing steel verified to be in compliance with plans and specifications.
- · Monitored placement of concrete for Wall from 1.4-J to 3.1-J
- · One set of 4 test cylinders were cast. Slump and temperature met job requirements.
- · Reinforcing steel verified to be in compliance with plans and specifications.
- · Observed drill and epoxy of imbed plate at column E-1 interior face as per RFI# 122 att.