



1100 W Cambridge Circle Drive  
Suite 700  
Kansas City, Kansas 66103  
913.627.9040

2121 Moodie Road  
Lawrence, Kansas 66046  
785.856.9600

2011 NW Topeka Blvd  
Topeka, Kansas 66608  
785.270.6447

## DAILY FIELD REPORT

CLIENT: Pearl Real Estate Company  
919 N East Street  
Indianapolis, Indiana 46202

PROJECT: Summit of West Pryor  
Apartments  
Lee's Summit, Missouri

ATTN: Brad Richey

DATE: 2/26/20

WEATHER: Sunny

CFS  
PERSONNEL: M. Simpson / G. Kenyon

TEMPERATURE: 30-50

REPORT #: 19-1125-dr- 83

### TYPE OF SERVICE BEING PERFORMED

**SOILS** COMPACTION MONITORING / TESTING

**DEVIATION FOUND: NO**

**MASONRY** GROUT / REINFORCING STEEL

**DEVIATION CORRECTED:**

**CONCRETE** PLACEMENT / REINFORCING STEEL

**ORIGINAL DEVIATION DATE:**

**OTHER** EPOXY INSTALLATION

### WORK ACCOMPLISHED THIS DATE:

#### *M. Simpson*

- Monitored placement of grout and inspected reinforcing steel at CMU, elevator shaft A walls, grouted at elevations 96.0 to 100.0 and 92.0 to 96.0 grout samples taken .
- One set of 3 grout cubes were cast. Slump met specifications.
- Reinforcing steel verified to be in compliance with plans and specifications.
- Monitored placement of concrete for column toppers (2') at 11.6, 11.2 , 10.6, 10 .4, 9.6 and 9.2 on J line.
- One set of 4 test cylinders were cast. Slump and temperature met job requirements.
- Reinforcing steel verified to be in compliance with plans and specifications.
- Observation of drill and epoxy placement of #4 & #5 dowels at columns 5.6 - J and 7.3 - J ,total 160 locations, 8" embed, vertical and lateral connections to wall J.

#### *G. Kenyon*

- Monitored placement and compaction of fill for South exterior wall backfill on Line 1 from A to J.
- Field compaction tests performed for South exterior wall backfill on Line 1 from A to J.
- Fill found to be in compliance with plans and specifications. Test results attached.