



1100 W Cambridge Circle Drive
Suite 700
Kansas City, Kansas 66103
913.627.9040

2121 Moodie Road
Lawrence, Kansas 66046
785.856.9600

2011 NW Topeka Blvd
Topeka, Kansas 66608
785.270.6447

DAILY FIELD REPORT

CLIENT: Pearl Real Estate Company
919 N East Street
Indianapolis, Indiana 46202

PROJECT: Summit of West Pryor
Apartments
Lee's Summit, Missouri

ATTN: Brad Richey

DATE: 2/19/20

WEATHER: Fair

CFS
PERSONNEL: A. Goodhope, P.E. / J. Moreland, EI

TEMPERATURE: 31-41

REPORT #: 19-1125-dr- 82

TYPE OF SERVICE BEING PERFORMED

OTHER STRUCTURAL STEEL

DEVIATION FOUND: NO

DEVIATION CORRECTED:

ORIGINAL DEVIATION DATE:

WORK ACCOMPLISHED THIS DATE:

- Observed the composite slab shear studs on the First Floor north of Grid Line 8. The studs were counted and also “pinged” to ensure adequate welding to the floor support beams. Previously missing studs had been added.
- Observed the metal floor deck attachment for the First Floor north of Line 8 using the Hilti submittal with the approval date of 01/24/20. Missing Hilti nails and sidelap fasteners were marked with pink paint, and the steel erection crew immediately installed them.
- Observed the bent plate dowels just West of Grid Line A between Grid Line 11.6 and 11.8; along Grid Line 11.8 from Grid Line C to C.3; along Grid Line C.3 from Grid Line 11.6 to 11.8; and along Grid Line C.7 from Grid Line 11.6 to 11.8. The dowels were found to be satisfactory.