CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRRES20192500Address:1821 SW MERRYMAN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection	ו:	Inspector:	Outcome:	Date:
Erosion Co	ontrol	Michael Harkins	Failed	Monday, March 09, 2020
Corrective	Action Required:			
1	DCM2 Erosion	DEFICIENT EROSION CONTROL INSTALLATION. NO FURTHER INSPE		
	Control	UNTIL ADEQUATE EROSION CONTROL PROVIDED.		
		**RESTORE EROSION ALONG THE REAR AND SIDE; 3/4" GRAVEL AT DR ENTRANCE		GRAVEL AT DRIVE

Comments: