

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20172529
Address: 261 NW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	Michael Harkins	Failed	Wednesday, March 18, 2020

Corrective Action Required:

1	FIRST FLOOR	Note: ground level need fire BLocking at foundation wall every10ft and at bottom of joist G 7 / G 8 Fire block at double wall
---	-------------	--

Corrective Action Required:

2	SECOND FLOOR	2nd floor - 206- studs laundry wall bored for plumbing Note: ground level need fire BLocking at foundation wall every10ft and at bottom of joist . Incomplete inspection on 1st
---	--------------	--

Corrective Action Required:

3	THIRD FLOOR	3rd floor- Dryer boxes 5 sided throughout building, all fire blocking at dbl wall construction and floor ceiling penetrations, basement level at foundation wall vertical to horizontal, Draft stops at no more than 2 units or 3000 sq ft. Submit Special inspection report for structural items. 311 dryer boxes.
---	-------------	---

Note: ground level need fire BLocking at foundation wall every10ft and at bottom of joist

Comments: