CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20191007

Address: 1844 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Occupancy Inspection - Codes

Residential

Tracy Deister

Pending

Corrective Action Required:

1 E3802.1 Bathroom

receptacles

GFCI PROTECTION. All 125-volt, single-phase, 15- and 20-ampere receptacles installed in bathrooms shall have ground-fault circuit-interrupter protection for

personnel.

Master bathroom plugs at double sink area are not working correctly. GFCI not

tripping.

Corrective Action Required:

2 Miscellaneous Correction Check all items outside. The ground was wet and no sod was installed at time

of inspection. TRACY DEISTER 03/27/2020 9:51 AM

Comments: