

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSUBD20181667
Address: 2601 SW PRYOR RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
DE - Erosion Sediment Control (ESC) Inspection	John DiMauro	Failed	Friday, March 27, 2020

Corrective Action Required:

1	Misc	EROSION CONTROL INSPECTION FAILED.
---	------	------------------------------------

There are areas around the basin where the silt fence is down and is allowing silt to run and collect into the basin.

The area around the creek needs to be graded and protected from site runoff.

There is an area near the entrance of the site that needs erosion control devices installed to protect the creek.

Steve Robbins and I met with the developer Doug Park to discuss the erosion control issues on Friday 3/6/2020. Doug said that he will get the areas noted protected and cleaned up asap.

Corrective Action Required:

2	Miscellaneous Correction	EROSION CONTROL INSPECTION FAILED.
---	--------------------------	------------------------------------

There are areas around the basin where the silt fence is down and is allowing silt to run and collect into the basin.

The area around the creek needs to be graded and protected from site

runoff.

There is an area near the entrance of the site that needs erosion control devices installed to protect the creek.

At the entrance of SW Pryor RD and SW River Run DR the silt fence has failed and is allowing silt and mud to collect on the street. Make corrections to the fence and clean the street asap.

Comments: