CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20173051

Address: 1980 SE BLUE PKWY, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Rated Assembly Inspection Khanh Nguyen Partial Thursday, April 02,

2020

Partial Correction:

1 ELEVATOR 1 ELEVATOR SHAFT:

1ST FL: 1" shaft liner ok; elev/shaft wall ok; check outer side screw pattern for

all walls

*Need to patch the wall above the restroom all the way to the steel beam.

2ND FL: 1" shaft liner ok; elev/shaft wall ok; check outer side screw pattern for

all walls

3RD FL: 1" shaft liner ok; elev/shaft wall ok; check outer side screw pattern for

all walls

ELEVATOR MECHANICAL SHAFT:

2ND FL: 1-hr lid ok; 1" shaft liner ok; outer layer ok

3RD FL: 1" shaft liner ok; outer layer ok

MID-BUILDING MECHANICAL SHAFT: 2ND FL: 1-hr lid ok, outer layer ok

3RD FL: 1-hr lid ok, outer layer ok

Partial Correction:

2 STAIR TOWER 1 The following areas:

1st Floor-outer side OK; inner side not ready

2nd-floor-outer side OK; inner side OK

3rd-floor-complete top out of inner side of exterior wall; outer side OK

***"STAIR TOWER 1 IS THE STAIR ENCLOSURE NEAR THE SE END OF BUILDING

Partial Correction:

3 STAIR TOWER 2 The following areas:

1st Floor-outer side OK; inner side not ready

2nd-floor-outer side OK; inner side OK

3rd floor-outer side OK; complete top out of inner side of exterior wall

***"STAIR TOWER 2 IS THE STAIR ENCLOSURE AT THE NORTH END OF

BUILDING

Comments: