

# Inspection Summary

Permit #: PRRES20193316, Building Permit - Residential

Address: 1626 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
Erosion Control	Steve Robbins	Failed	Tuesday, April 07, 2020

Corrective Action Required

- 1 Failing erosion control is causing silt to fill in the swale behind the lot. Please take a look and make corrections.

Comments: