## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRSUBD20190654

Address: 2030 NW OBRIEN RD, LEES SUMMIT, MO 640812020 NW OBRIEN RD, LEES SUMMIT, MO 64081500 NW PRYOR RD, LEES SUMMIT, MO 64081450 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
DE - St Inspec		truction Ronald Paynter	Partial	Tuesday, April 14, 2020
Inform	ational:			
1	Misc	line 2. Curb inlet box 2 They also set storm lin	2-5 was manufactured v es A and B. Field inlet y need to reshoot elev	6. They are working on storm wrong and has to be replaced. B-0 is setting high compared to rations and see what is wrong
Inform	ational:			
2	Misc	Darren's crew reset the set 60 ft of storm pipe.		2-5 and curb inlet 2-6. They also
Inform	ational:			
3	Misc			ft of storm pipe. They also 2-6 and 17-1. RP 10-25-19
Inform	ational:			
4	Misc			ded manhole 10-1, curb inlets rugated HDPE storm pipe. RP
Inform	ational:			
5	Misc	Jim's crew set storm m inch HPDE storm pipe.		let 6-2 along with 130 ft of 24
Inform	ational:			
6	Misc	Jim's crew set storm o	utlet 6-0 and curb inlet	6-3 along with 110 ft of 30 inch

and 40 ft of 24 inch HDPE storm pipe. RP 11-25-19   Informational:   7 Misc   Jim's crew set field inlet 6-4 along with 160 ft of 18 inch HDPE storm pip RP11-26-19   Informational:   8 Misc   Jim's crew encountered a rock shelf on storm line 6 that they have to be out. The set 110 ft of 15 inch HDPE storm pipe. RP 11-27-19   Informational:   0   Misc	eak 19.
7MiscJim's crew set field inlet 6-4 along with 160 ft of 18 inch HDPE storm pip RP11-26-19Informational:Im's crew encountered a rock shelf on storm line 6 that they have to be out. The set 110 ft of 15 inch HDPE storm pipe. RP 11-27-19Informational:	eak 19.
8 Misc Jim's crew encountered a rock shelf on storm line 6 that they have to be out. The set 110 ft of 15 inch HDPE storm pipe. RP 11-27-19 Informational:	19.
out. The set 110 ft of 15 inch HDPE storm pipe. RP 11-27-19 Informational:	19.
0 Mice lim'r grow gamalatad starm ling Cand is mawing an ta starry ling - 0	
9 Misc Jim's crew completed storm line 6 and is moving on to storm lines 8 and RP 12-3-19	19.
Informational:	19.
10MiscJim's crew completed storm line 6 and is moving on to storm lines 8 and RP 12-3-19	
Informational:	
11 Misc Jim's crew completed installation of storm line 9. RP 12-3-19 Informational:	
12 Misc Jim's crew completed storm lines 7 and 8. They also laid 600 ft of 15 incl HDPE storm pipe. RP 12-6-12	۱
Informational:	
13MiscJim's crew has completed storm line 4. They have also set MH 4-1 and c inlets 4-2 and 4-3. RP 1-28-20	urb
Informational:	
14MiscJim's crew completed storm line 3. They set curb inlets 3-3, 3-4, 3-5 and RP 2-7-20	3-6.
Informational:	
15MiscDarren's crew has started working on storm line 14 between end sectioand manhole 14-1. RP 3-3-20	n 14-0
Informational:	
16 Misc Darren's crew set storm manhole 14-2. RP 3-5-20	
Informational:	
17MiscDarren's crew finished storm line 15 and set manhole 15-1 and curb inle15-2 and 15-3. RP 3-30-20	ts
Informational:	
18MiscDarren's crew finished storm line 15 and set manhole 15-1 and curb inle15-2 and 15-3. RP 3-30-20	ts
Informational:	
19MiscDarren's crew completed storm section from 14-2 to 14-3. They also setinlet 14-3. RP 3-31-20	curb
Informational:	
20 Misc Darren's crew set manhole 14-4 and field inlet 14-5. That completes sto line 14. RP 4-2-20	rm
Informational:	
21MiscDarren's crew has set end of storm 13-0, manhole 13-1 and curb inlet 134-9-20	-2. RP
Informational:	
22MiscDarren's crew set curb inlets 13-3 and 13-4. That completes storm line 14-13-20	.3. RP

## Comments: