CITY OF LEE'S SUMMIT

Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20192766

Address: 1104 NE GOSHEN CT, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Khanh Nguyen Failed Wednesday, April 15,

Residential 2020

Corrective Action Required:

1 Misc FRAMING:

- -Install support device at trimmer joist connection to ledger board
- -Fb mud wall from soffit/roof
- **near garage door
- -Fb basement wall space vertically every ten ft or less; Fb basement closet&bath wall from furdown ceiling space
- **cannot use 1/2" board for fireblocking; fb hole at top of vertical fireblocking; wall in bath still not fireblocked from ceiling space; if insulation used as fireblocking must be min 16" from ceiling level down; etc
- -Nail all hanger nail holes at stair double joist-double joist connection
- -Relocate I beam support columns at stair and bedroom wall to correct locations
- **see plan for correct column locations

PLUMBING:

- -Protect water lines at master shower
- -Install wye or combination long sweep fitting at vertical to horizontal sewer connection

MECHANICAL:

-Close off all return air from the basement ceiling soffit; seal penetrations of

return air space

Comments: