CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192495 Address: 2931 NE INDEPENDENCE AVE, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
In-wall Inspection		Khanh Nguyen	Failed	Thursday, April 30, 2020
Corrective	Action Required:			
1	Misc	 -Protect plumbing with BOCA plates at bottom wall plate **Not done as required per IPC 305.6. Code requires protection to extend min 2" above the wall sole plate, where the plumbing is less than 1.25" from wood surface -Med gas wall must be rated one hour with exposure on both sides **Frame the 1-hr wall to roof deck for 5/8" type x rock on both sides. Have architect address what needs to be done with the truss and wall not aligned for 		
		5/8" type x rock		
		-Install hold down anchors	for east shear walls	
		**Have architect address v rear shear wall	vhere foundation hold-dowr	is are required for the
		**OK TO INSULATE WALLS **DO NOT ROCK FURTHER		

Comments: