CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSITE20193581

Address: 2001 NW SHAMROCK AVE, Unit:IR, LEES SUMMIT, MO 640812001 NW SHAMROCK AVE, LEES

SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

DE - Erosion Sediment Control Ronald Paynter Failed Tuesday, May 12, 2020

(ESC) Inspection

Corrective Action Required:

1 Misc Went to meet Norm from Axiom to discuss the temporary silt trap for the

detention basin. When I arrived on site, I saw that Bair Excavating worked over the weekend and they stripped the entire site of vegetation along with not installing the silt trap. Will meet again on site tomorrow to go over these

problems with the contractors. RP 2-24-20

Informational:

2 Misc Erosion controls are in place along with silt trap. Gutter buddy's are placed

along Pryor protecting the storm system. RP 3-7-20

Corrective Action Required:

3 Misc After hauling trucks on site all day yesterday, rocks were still in roadway and

curb inlets (protected with gutter buddies) packed with silt this morning. Developer and City Inspector cleaned everything up that the sub contractor

(Bair Excavating) failed to due correctly last night. RP 3-27-20

Informational:

4 Misc Norm from Axiom and Zack from Larry Bair have taken turns running the

sweeper to keep Pryor Rd clean. I talked Norm and Nick from Larry Bair about also controlling the dust that is blowing across the roadway. Some of

the dust is also coming from the fire station 3 project. RP 4-9-20

Corrective Action Required:

5 Misc No area inlet protection has been placed around catch basin B3, and curb

Comments: