

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20193370
Address: 2017 NE BLUESTONE DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Khanh Nguyen	Failed	Tuesday, May 12, 2020

Corrective Action Required:

1 Misc

FRAMING:

- Remove the roof underlay from roof ventilation opening
- The double joists under the great room is too far out from foundation wall. Sister another joist to this to triple
- Nail triple stud shoe at kitchen/laundry wall. Have the engineer ok this bored triple stud reinforced with the stud shoe. Framers-install double joist under this point load

ELECTRICAL:

- Protect wiring at mud wall plate; stud near end of kitchen countertop
- Protect wiring within six ft of attic access above master bedroom
- Bond gas piping
- Protect wiring running across bottom of joists near panel
- Protect SE conductor connections to power bus bars at panel

PLUMBING:

- Nail triple stud shoe at kitchen/laundry wall. Have the engineer ok this bored triple stud reinforced with the stud shoe. Framers-install double joist under this point load

**OK TO INSULATE

Comments: