

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSUBD20190654

Address: 2030 NW OBRIEN RD, LEES SUMMIT, MO 640812020 NW OBRIEN RD, LEES SUMMIT, MO 64081500
NW PRYOR RD, LEES SUMMIT, MO 64081450 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
DE - Erosion Sediment Control (ESC) Inspection	Ronald Paynter	Partial	Friday, May 29, 2020

Corrective Action Required:

1	Misc	Silt is washing up on 113, 109, 105 and 101 NW Cody Dr. Silt fence is down in one spot. Might need to design a silt trap basin for this area. Silt was also washing down the field inlet behind 117 NW Cody Dr. RP 8-26-19
---	------	--

Corrective Action Required:

2	Misc	Silt fence protecting Ambersham off Whitman has washed out and is allowing silt to leave the work site. Fencing needs to be repaired and SWPPP needs to be re-evaluated to avoid further violations. Future violations could lead to stop work orders being issued. RP 8-28-19
---	------	--

Corrective Action Required:

3	Misc	Silt fence on Ambersham has been breeched in numerous spots, dumping silt down Ambersham and Whitlock. Need to get repair erosion control and remove silt from roadways. RP 5-28-20
---	------	---

Informational:

4	Misc	Silt has been swept up from the roadways. Welch Erosion still needs to repair erosion control devices. RP 5-29-20
---	------	---

Comments: